




REV.	DESCRIPTION	ECN	DATE	BY
A	NEW DRAWING	C-5621	07/28/2008	TLK
B	REPLACE WC PART NO. WITH VENDOR PART NO.	7050	5/26/2009	EFR

 REPAIR KIT SRK811				HUBCAP REPLACEMENT KIT
ITEM	VENDOR PART NO.	OLD PART NO.	QTY	DESCRIPTION
1	2208Z1118	18080-032	1	HUB CAP GASKET
2	343-5110	18080-037	1	HUBCAP 8K WINDOW STY
3	WA 15	18080-034	4	WASHER FLAT
4	S2562	18080-035	4	BOLT F/ HUBCAP



MATERIAL INFO.	DEPTS AFFECTED	TOLERANCES (EXCEPT AS NOTED)	DESCRIPTION: HUBCAP REPLACEMENT KIT		
STEEL PART NO.	60/65	DECIMAL + - .03	PREVIOUS ASSY: -		 Watson & Chalin <small>MANUFACTURING INC.</small> Watson Suspension Systems
MATERIAL:	-	FRACTIONAL + - 1/32	SUSPENSION MODEL: SL08XX	SCALE: 1:9	
WEIGHT:	-	ANGULAR + - 0.5°	DATE: 07/28/2008	DRAWN BY: TLK	SIZE: A
					DRAWING NO: SRK811