


REV.	DESCRIPTION	ECN	DATE	BY
A	NEW DRAWING	C-4261	10/23/2006	TEG
B	REPLACE WC PART NO. WITH VENDOR PART NO.	7050	5/26/2009	EFR
C	ITEM #4 WAS A1205N2432	7204	9/29/2009	EFR

B REPAIR KIT SRK813				HUB MAINTENANCE KIT
ITEM	VENDOR PART NO.	OLD PART NO.	QTY	DESCRIPTION
1	25820	-	1	OUTER BEARING RACE 8K
2	JM207010	-	1	INNER BEARING RACE 8K
3	JM207049A	18080-026	1	INNER BEARING 8K
4	28758 C	18080-025	1	OIL SEAL 8K
5	25877	18080-027	1	OUTER BEARING 8K



MATERIAL INFO:	DEPTS AFFECTED:	TOLERANCES (EXCEPT AS NOTED):	DESCRIPTION: HUB MAINTENANCE KIT		
STEEL PART NO:	60/65	DECIMAL ± .03	PREVIOUS ASSY: -		 WATSON & CHALIN MANUFACTURING INC. Watson Suspension Systems
MATERIAL:	-	FRACTIONAL ± 1/32	SUSPENSION MODEL: SL08XX	SCALE: 1:9	
WEIGHT:	-	ANGULAR ± 0.5°	DATE: 10/23/06	DRAWN BY: TEG	SIZE: A
					DRAWING NO: SRK813