


REV.	DESCRIPTION	ECN	DATE	BY
A	NEW DRAWING	C-5621	07/28/2008	TLK
B	REPLACE WC PART NO. WITH VENDOR PART NO.	7050	5/26/2009	EFR

REPAIR KIT SRK804-10/-20 KIT				TIEROD REPAIR KIT
ITEM	VENDOR / WC PART NO.	OLD PART NO.	QTY	DESCRIPTION
1	CHART	CHART	1	TIEROD END 8K
2	90608	18080-036	1	NUT (INCL TIEROD END ASSY.)
3	K2412	18080-019	1	COTTER PIN



REPAIR KIT	LH/RH	ITEM #1 VENDOR NO.	ITEM #1 OLD NO.
SRK804-10	L.H.	X31444005	18080-020-10
SRK804-20	R.H.	X31444006	18080-020-20

MATERIAL INFO:	DEPTS AFFECTED:	TOLERANCES (EXCEPT AS NOTED):	DESCRIPTION: TIEROD REPAIR KIT (MERITOR)	
STEEL PART NO:	60/65	DECIMAL ± .03	PREVIOUS ASSY:	-
MATERIAL:	-	FRACTIONAL ± 1/32	SUSPENSION MODEL:	SL08XX
WEIGHT:	-	ANGULAR ± 0.5°	SCALE:	1:6
			DATE:	07/28/2008
			DRAWN BY:	TLK
			SIZE:	A
			DRAWING NO:	SRK804

