


REV.	DESCRIPTION	ECN	DATE	BY
A	NEW DRAWING	C-4261	10/23/2006	TEG
B	ITEM #2 WAS 11222,4 WAS 19040F-113	C4979	12/10/2007	JFF
C	ADDED WASHER 11222	C-6317	4/29/2009	TEG

SERVICE REPAIR KIT SRK2089-1

SL2089 BUSHING REPAIR KIT

ITEM	PART NO.	QTY	DESCRIPTION
1	10050	2	PIVOT BSHG 3.5 OD X 1.125
2	10045 \triangle_B	8	WASHER FLAT HARDENED 1.12
3	12789	2	BUSHING, AX SEAT SL1800
4	10023 \triangle_B	4	NUT TOPLOCK 1.13UNF GR8
5	19365	2	CAPSCREW 1.12 X 9.00 UNF
6	19366	2	CAPSCREW 1.12 X 11.50 UNF
\triangle_C 7	11222	8	WASHER FLAT 1.12

DEPTS AFFECTED	TOLERANCES (EXCEPT AS NOTED)	DESCRIPTION: SRK KIT		
7300	DECIMAL $\pm .03$	PREVIOUS ASSY: VARIES		 Watson Suspension Systems
	FRACTIONAL $\pm 1/32$	SUSPENSION MODEL: VARIES	SCALE: 1:1	
	ANGULAR $\pm 0.5^\circ$	DATE: 10/23/06	DRAWN BY: TEG	SIZE: A
				DRAWING NO: SRK2089-1